

The Woodlands High School - Main Campus

- Robotics lab & science classrooms addition
- Add voice evacuation system
- Replace auditorium seats
- Camera conversion - analog to IP
- Deep sinks in the art rooms
- Football turf conversion
- KILN replacements
- LED stage lighting and controls
- Passage to band enclosed
- Provide concrete pad at practice field entrance
- Provide miscellaneous roof repairs
- Provide new practice hitting net at softball field
- Relocate HVAC equipment in auditorium
- Remove and replace exterior building waterproofing sealants throughout entire facility
- Safety and security upgrades
- Softball turf conversion
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Upgrade wireless access points
- Add wood dance floor
- Baseball turf conversion (*Scotland Yard is located at McCullough JH*)

The Woodlands High School - 9th Grade Campus

- Camera conversion - analog to IP
- Deep sinks in the art rooms
- Remove all classroom technology panels and related cabling
- Remove and replace exterior building waterproofing sealants throughout entire facility
- Safety and security upgrades
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Wet glaze seal all deteriorated and damaged window glazing gaskets
- KILN replacements
- LED stage lighting
- Re-cable technology cabling where classroom technology panels were removed throughout campus

McCullough Junior High

- Address drainage inlet at lift station
- Baseball turf conversion (*Scotland Yard is the baseball field for TWHS*)
- Bathroom upgrades in boys locker rooms
- Paint walls in kitchen



McCullough Junior High (cont'd)

- Remove and replace exterior building waterproofing sealants throughout entire facility
- Remove and replace south driveway near temporary buildings
- Remove existing tech panel and cabling; relocate power outlet to below; and repair repaint wall
- Repair sidewalk
- Replace and expand cold storage assembly
- Replace exhaust hoods
- Replace existing commons curtain wall system
- Reseal restripe south driveway asphalt
- Reseal south asphalt parking lot
- Restripe fire lane
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Wet glaze seal all deteriorated and damaged window glazing gaskets
- Safety and security review

Mitchell Intermediate

- Install ceiling mounted projectors in designated rooms
- Remove and replace service drive, swale and curb
- Remove classroom technology panels
- Replace sports court gym flooring per district standards
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Upgrade technology cabling where technology panels were removed throughout building
- Safety and security review

Wilkerson Intermediate

- PE Classroom/Gym Addition
1 of 2 intermediates in CISD without designated PE classroom/gym space
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Install catwalk and ladder
- Install data and power to Library computer tables under floor
- DAS Repeater and First Responder
- Fire Alarm Voice Evac System Upgrade
- Provide access on service/kitchen drive with concrete
- Provide district standard projector in designated rooms
- Regrade around additional parking lot on west side
- Relocate transformer in custodial storage
- Relocate transformer for technology
- Remove and replace exterior building waterproofing sealants throughout entire facility
- Remove skylights, install new finishes, lighting and roof at entry corridor



Wilkerson Intermediate (cont'd)

- Replace (5) soffit light fixtures
- Replace all pole lights with LED
- Replace basketball court with concrete
- Reseal and re-stripe asphalt south parking lot
- Wet glaze seal all deteriorated and damaged window glazing gaskets
- Safety and security review

Buckalew Elementary

- Add outlet for changing table
- Add outlet for the water closet
- Address drainage at play area
- Install new classroom projection system
- Provide roof access ladder
- Remove and replace exterior building waterproofing sealants throughout entire facility
- Repurpose dish room
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Wet glaze seal all deteriorated and damaged window glazing gaskets
- Safety and security review

Bush Elementary

- Install additional fencing (*site fence is not continuous around property*)
- Add outlet for personal lift
- Replace projectors in designated rooms
- Renovate restrooms to accommodate changing tables
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Safety and security review

Deretchin Elementary

- Remove and replace exterior building waterproofing sealants throughout entire facility
- Restripe fire lane
- Restripe lots
- Stage Curtains - Fireproofing
- Stage Curtains - safety, rigging & tracks
- Wet glaze seal all deteriorated and damaged window glazing gaskets
- Safety and security review



Galatas Elementary

- ADA modifications to gym/cafeteria, restrooms and parking at bus loop
- Install 24/7 air conditioning for technology
- Electrical updates for kitchen devices
- Add outlets for personal lift
- Remove old 6"x4" metal covers on thermostats in all classrooms
- Patch and repair wall where thermostat covers were removed and repaint wall
- Provide district standard projector in designated rooms
- Repair miscellaneous pipe insulation
- Replace air handling units throughout, including ductwork
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Upgrade HVAC controls throughout the building
- Upgrade mechanical boiler with high efficiency heater
- Safety and security review

Glen Loch Elementary

- HVAC Overhaul
- Cover existing storm piping above slab with fire wrap
- Upgrade air conditioning for technology
- Install emergency generator and system
- Install occupancy sensors throughout building
- Add outlets for personal lift
- Provide district standard cable management in designated room
- Provide district standard projector in designated rooms
- Provide hot water in janitor's closets
- Provide two roof access ladders
- Reinstall carpet
- Remove technology box in kitchen office
- Repair water leak at exterior windows in designated rooms and replace gypsum board and finishes
- Replace exterior soffit light fixtures
- Replace exterior wall mounted light fixtures at exit doors adjacent to gymnasium
- Replace ceiling tile and grid throughout school
- Replace electrical equipment throughout school
- Replace old air handling equipment and ductwork
- Replace pneumatic controls with (direct digital control) DDC
- Deep sinks in the art rooms
- Replace Pneumatic Fire Dampers with electronic
- Reroute storm and fire sprinkler piping
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Safety and security review



Powell Elementary

- Upgrade air conditioning for technology
- Install ceiling projectors in designated areas
- Add outlets personal lift
- Provide miscellaneous repairs at walls
- Remove and replace exterior building waterproofing sealants throughout entire facility
- Repair miscellaneous pipe and duct insulation in Central Plant
- Stage Curtains - fire proofing
- Stage Curtains - safety, rigging & tracks
- Upgrade HVAC controls throughout the building
- Wet glaze seal all deteriorated and damaged window glazing gaskets
- Safety and security review

Tough Elementary

- Address washout near drive near swimming pool
- Remove and replace exterior building waterproofing sealants throughout entire facility
- Replace sports floors in gym
- Wet glaze seal all deteriorated and damaged window glazing gaskets
- Deep sinks in the art rooms
- KILN replacements
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Safety and security review

