

- Address washout near drive near swimming pool
- Remove and replace exterior building waterproofing sealants throughout entire facility
- Replace sports floors in gym
- Wet glaze seal all deteriorated and damaged window glazing gaskets
- Deep sinks in the art rooms
- KILN replacements
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Safety and security review

Check out the projects for other feeder schools.

The Woodlands High School - Main Campus

- Robotics lab & science classrooms addition
- Add voice evacuation system
- Replace auditorium seats
- Camera conversion - analog to IP
- Deep sinks in the art rooms
- Football turf conversion
- KILN replacements
- LED stage lighting and controls
- Passage to band enclosed
- Provide concrete pad at practice field entrance
- Provide miscellaneous roof repairs
- Provide new practice hitting net at softball field
- Relocate HVAC equipment in auditorium
- Remove and replace exterior building waterproofing sealants throughout entire facility
- Safety and security upgrades
- Softball turf conversion
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Upgrade wireless access points
- Add wood dance floor
- Baseball turf conversion (*Scotland Yard is located at McCullough JH*)

The Woodlands High School - 9th Grade Campus

- Camera conversion - analog to IP
- Deep sinks in the art rooms
- Remove all classroom technology panels and related cabling
- Remove and replace exterior building waterproofing sealants throughout entire facility



The Woodlands High School - 9th Grade Campus (cont'd)

- Safety and security upgrades
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Wet glaze seal all deteriorated and damaged window glazing gaskets
- KILN replacements
- LED stage lighting
- Re-cable technology cabling where classroom technology panels were removed throughout campus

McCullough Junior High

- Address drainage inlet at lift station
- Baseball turf conversion (*Scotland Yard is the baseball field for TWHS*)
- Bathroom updates in boys locker rooms
- Paint walls in kitchen
- Remove and replace exterior building waterproofing sealants throughout entire facility
- Remove and replace south driveway near temporary buildings
- Remove existing tech panel and cabling; relocate power outlet to below; and repair repaint wall
- Repair sidewalk
- Replace and expand cold storage assembly
- Replace exhaust hoods
- Replace existing commons curtain wall system
- Reseal restripe south driveway asphalt
- Reseal south asphalt parking lot
- Restripe fire lane
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Wet glaze seal all deteriorated and damaged window glazing gaskets
- Safety and security review

