

- Upgrade HVAC controls
- Clean storm inlets
- Provide code required combustion air to Boiler Room
- Provide district standard cable management in designated classrooms
- Provide district standard projector in designated classrooms
- Provide hot water to all janitor sinks
- Remove old 6"x4" metal covers on thermostat in all classrooms
- Replace kitchen water heater
- Reseal asphalt parking lot
- Stage Curtain - fire proofing
- Stage Curtain - safety, rigging & tracks
- Safety and security review

Check out the projects for other feeder schools.

TW College Park High School

- 10 classroom addition
- Band Tower
- Baseball turf conversion
- Camera conversion - analog to IP
- Carpet
- Fire alarm compliance, safety upgrades & life cycle
- Football turf conversion
- HVAC equipment in auditorium, dampen and seal
- LED stage lighting
- Provide access to maintenance pad at new athletic additions
- Remove and replace exterior building waterproofing sealants throughout entire facility
- Repaint
- Restripe fire lane
- Safety and security upgrades
- Shop space for theater
- Softball turf conversion
- Stage Curtains - fire proofing
- Stage Curtains - safety, rigging & tracks



Knox Junior High

- Replace basketball goals in both gyms
- Intro to robotics lab
- New gym floors
- Provide district standard projector in designated classrooms
- Reconstruct tennis courts
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Safety and security review

Wilkerson Intermediate

- PE Classroom/Gym Addition
1 of 2 intermediates in CISD without designated PE classroom/gym space
- Stage Curtains - fire proofing
- Stage Curtains - safety rigging on tracks
- Install catwalk and ladder
- Install data and power to Library computer tables under floor
- DAS Repeater and First Responder
- Fire Alarm Voice Evac System Upgrade
- Provide access on service / kitchen drive with concrete (400x10)
- Provide district standard projector in designated rooms
- Regrade around additional parking lot on west side
- Relocate transformer in custodial storage
- Relocate transformer in MDF
- Remove and replace exterior building waterproofing sealants throughout entire facility
- Remove skylights, install new finishes, lighting and roof at entry corridor
- Replace (5) soffit light fixtures
- Replace all pole lights with LED
- Replace basketball court with concrete
- Reseal and re stripe asphalt south parking lot
- Wet glaze seal all deteriorated and damaged window glazing gaskets
- Safety and security review

